UNITED STATES GEOLOGICAL SURVEY Engineering Equivalent geologic	Description and	Other C-		T			ne Boulder quadrangle, Colo		<u></u>	Colorado	OPEN FILE Sheet 4 of	
geology unit (s) unit name and map symbol	thickness	Other features	Topographic form and surface relief	Weathering and ancient soils	Workability	Surface drainage and erosion	Ground water	Suitability for waste disposal	Foundation stability	Slope stability	Probable earthquake stability	
swelling claystone and siltstone cs-ms (Baculites grandis And B. clinolobatus zones, including basal part of upper transition member.	claystone, silty, and siltstone, very clayey to sandy: firmly cemented, dense and hard; overconsolidated; laminated, snaly; bedding even, persistent laterally; light gray where unweathered; composed chiefly of clay minerals (calcium montmorillonite and mixed-layer illite-montmorillonite are about equally abundant) and quartz, plus minor amounts of feldspar, calcite, and dolomite. About 1,000 ft thick. Contains sparse 1/4- to 2-inthick beds of bentonite composed mostly of calcium montmorillonite, and sparse hard, brittle calcareous concretions as much as 18 in. longest dimension.	Claystone and siltstone: PVC2/ rating, 3.4-7.4, marginal to very critical; swell index, 2,500 5,900 psf. Bentonite: FVC2/ rating greater than 10, very critical swell index greater than 14,000 psf. Dip of beds: 3° E. to 22° W.: forms trough of syncline with axis trending north to south along 28th Street, Boulder.	alluvium and colluvium covered plains; slopes as steep as 15° along flanks of mesas east of mountain front.	The state of the s	including tractor- drawn scrapers and backhoes. Compaction: easy; sheepsfoot rollers commonly used. Drilling: moderately easy.	Infiltration: negligible. Runoff: rapid; water may accumulate in local shallow depressions for as long as a week. Susceptibility to erosion: moderate b gully wash; high by sheet wash; moderate by wind deflation where loosened by plowing or construction. Difficult to reestablish regetation.	decomposed subzone; very low to negligible in subzone jointed by desiccation. Yield to wells: negligible; locally yields very small	slow. Dump sites: excellent because excavation easy and risk negligible of ground-water pollution.	Very poor to fair, depending on load, foundation design, and change in moisture content after construction. Locally expands excessively, and exerts high swelling pressures when moisture content increases. Bentonite beds unsuitable: expand exorbitantly, exert very high swell pressures, and have low snearing strength. Susceptibility to frost neave high.	cut perpendicular to strike of bedding, or where bedding dips away from cut, slopes cut at 1 horizontal to 1 vertical probably	good. Locally poor at top of high cuts or on steep hillsides.	Source of raw material for manufacture of expanded shale for lightweight aggregate. Source of poore quality impervious fill and binder material.
lower transition member through Baculites obtusus B. jenseni, B. eliasi, and B. baculus zones; Graneros Shale	minor siltstone, clayey to sandy: firmly cemented, dense and hard; overconsolidated; laminated to fissile; bedding even, persistent laterally; gray to black where unweathered; composed chiefly of clay minerals (mixed-layer illite- montmorillonite slightly more abundant than illite), and	Claystone and shale: PVC2/ rating, 1.3-3.4, noncritical to mar- ginal; swell index, 1,150-2,800 psf. Bentonite: PVC2/ rating, 1.3-7.7, non- critical to very critical; swell index, 1,100-6,200 psf. Dip of beds: 25° E. in northern part of mapped area to 50° W. along west College Avenue, Boulder.	Same as for above.	Where buried by surficial deposits, uppermost zone of unit typically composed of two subzones: upper, generally 2-4 ft thick, altered to light gray very stiff to hard clay (CL, ML, CL-ML3/), and lower subzone, generally 2-8 ft thick, compose of hard claystone and shale jointed chiefly by desiccation into small conchoidal fragments. Where not covered by surficial deposits, upper subzone commonly removed by erosion; lower subzone as much as 15 ft thick; highly susceptible to weathering.	a i	Infiltration: Same as for above. Runoff: Same. Susceptibility to erosion: Same.	Permeability: Same as for above. Yield to wells: Same. Quality: Same. Use: Same.	Septic systems: Same as for above. Dump sites: Same.	Poor to fair depending upon load, foundation design, and change in moisture content after construction. Generally expands moderately, and exerts moderate swelling pressures when moisture content increases. Bentonite beds unsuitable: expand excessively, exert high swell pressures, and have low shearing strength. Susceptibility to frost heave high.		Same as for above.	Source of poor- quality impervious fill and binder material.
siltstone and shale ms-sh from top of Hygiene Sandstone Member through Baculites reesideil/zone, inclusive; Niobrara Formation (part): Smoky Hill Shale Member; Greenhorn Limestone; Carlile Shale.	sandy, and minor claystone and sandstone: well cemented, very dense and very hard; over-consolidated; thinly laminated to fissile; bedding even, persistent laterally; gray to olive gray where unweathered; composed chiefly of quartz, calcite, and clay minerals (mixed-layer		Gently rolling alluvium- and colluvium-covered plains; slopes as steep as 25° along flanks of mesas east of mountain front.	Where buried by surficial deposits, uppermost zone of unit typically composed of two subzones: upper, gene ally 1-2 ft this k, altered to ol ve-gray to darker ay clayey to sandy ilt (ML, CL, SM3/), and lower subzone, generally 4-6 ft thick jointed chiefly by desiccation into small blocks and conchoidal fragments of very hard siltstone and shale. Where not covered by surficial deposits, upper subzone commonly removed by erosion; lower subzone as much as 10 ft thick; moderately to highly susceptible to weathering.	to depth of 10 ft with power equipment including tractordrawn scrapers and backhoes. Moderately difficult locally in some siltstone, concretion, and sparse sandstone beds. Compaction: moderately easy; sheepsfoot rollers commonly used. Drilling: moderately easy to moderately difficult.	Runoff: Same. Susceptibility to erosion. Same.	Permeability: Same as for above. Yield to wells: Same. Quality: Same. Use: Same.	Septic systems: generally unsatisfactory; percolation generally too slow. Dump sites: generally good because risk negligible of ground-water pollution: locally fair because siltstone and concretions moderately difficult to excavate.	Generally fair. Expands slightly and exerts generally low swelling pressures when moisture content increases. Bentonite beds unsuitable: most expand excessively, exert high swell pressures, and have low shearing strength. Susceptibility to frost heave moderate.		Same as for above.	Same as for above.
nonswelling claystone and siltstone cs-ms Baculites obtusus 1/ zone to base of Hygiene Sandstone Member.	unweathered; composed chiefly of quartz, clay minerals (mixed-	Claystone and siltstone: PVC2/ rating, 0.8-1.8, noncritical; swell index, 800-1,500 psf. Kaolinitic clay: PVC2/ rating, 2.6, marginal; swell index, 1,700 psf. Dip of beds: about 200 E. north of Fourmile Canyon; 300 E., through vertical, to 800 W. south of Fourmile Canyon.	Gently rolling alluvium- and colluvium-covered plains; slopes as steep as 15° along flanks of mesas east of mountain front.	typically composed of		Infiltration: Same as for above. Runoff: Same. Susceptibility to erosion: Same.	Permeability: Same as for above. Yield to wells: Same Quality: Same. Use: Same.	Septic systems: Same as for "Swelling clay- stone and silt- stone (cs-ms)." Dump sites: Same.	May in places swell slightly and exert low swelling pressures when moisture content increases. Beds of kaolinitic clay unsuitable: most swell moderately, exert moderate swell pressures, and have low shearing strengths. High susceptibility to frost heave.		Same as for above.	Same as for above.
claystone, and limestone ms-cs-ls Ralston Creek Formation.	cemented. Beds lenticular, interlayered, and of variable thickness and lateral extent; varicolored. Clay minerals in the claystone chiefly mixed-layer illite-montmorillonite and illite; in some beds kaolinite equally abundant. Some gypsum and anhydrite in lower part. As much as 300 ft thick.	characteristically noncritical. Gypsum may dissolve, and anhydrite may swell with application of water. Dip of beds: 15°-50° E. in northern part of mapped area; 15° E. to vertical in southern part.	hogback; maximum slope ranges from 15° to 25°.	Where naturally exposed, surface of siltstone and sandstone commonly case-hardened; limestone surface roughened and pitted by solution. Claystone, commonly buried by surficial deposits, generally fractured and weakened to depth of 3-6 ft below base of surficial deposit. Unit as whole moderately susceptible to weathering.	difficult; hauling equipment, smooth-tire rollers commonly used. Drilling: moderately difficult.	where protected by surficial deposits, but high where	Permeability: varies, probably very low to negligible. Water table: generally none. Yield to wells: not known to yield water to wells in area.	Septic systems: generally unsatisfactory; percolation generally too slow. Dump sites: poor chiefly because slope too steep and risk moderate of pollution passing into nearby aquifers.	Light structures: generally fair to good; locally may expand and exert moderate swelling pressures because of moisture change in sparse lense of swelling claystone or anhydrite. Heavy structures: poor; may settle unevenly because of local variations in bearing strength, or loss of gypsum by leaching.	Usually good, because most beds dip into hillside.	Good.	Source of clay for brick and tile.
ms (part)	fine grained; moderately to well cemented; thin-bedded, slabby to laminated, shaly; bedding even, persistent laterally; reddish brown; composed chiefly of calcite, quartz, and mica with minor amounts of clay minerals	Siltstone: PVC2/ rating, characteristically noncritical. Gypsum may dissolve and anhydrite may swell with application of water. Dip of beds: 45°-60° E. Limestone (map unit, ls) about 150 ft above base and between two parts of unit.	Valley along hogbacks; maximum slopes range from 200 to 300	In natural exposures, moderately resistant to moderately susceptible to weathering. Where buried by surficial deposits, uppermost zone of unit commonly altered and weakened to depth of 2-6 ft below base of surficial deposit.	easy to depth of 6 ft with most power equipment, moderately difficult below 6 ft; locally may require blasting. Compaction: moderately difficult; hauling equipment, pneumatic- and smooth-tire rollers commonly used. Drilling: moderately difficult.	Infiltration: slow. Runoff: medium to rapid. Susceptibility to erosion: moderately resistant where unweathered similar to "Pebbly sand, silt, and clay (SCp)" where weathered.	slope of surface; water moves mostly along fractures	Septic systems: generally unsatisfactory chiefly because easily excavated material generally too thin for proper burial of system and risk moderate of pollution passing through fractures into water supplies. Dump sites: poor because excavation moderately difficult.	Generally good. Poor for most structures in lower part because of possible swelling of anhydrite, or settling because of leaching of gypsum.	Mostly fair. Poor to hazardous if bedding surfaces are undercut. Rock debris may slide on dip slope.	Good.	Source of poor quality fill.
sandstone ss	grained, well sorted, loosely to	Porous, minor aquifer near outcrop. Dip of beds: 30°-60° E. in northern part of mapped area; 85° E. to vertical in southern part.	Narrow ledge of light-colored rock parallel to hogback crest and along east side of valley formed in "Red siltstone (ms)."	In natural exposures, moderately resistant to weathering; commonly leached of calcareous cement and weakened to depth of about 1 ft below surface of unit.	Excavation: moderately difficult with heavy tractor-drawn rippers and scrapers. Compaction: moderately difficult with hauling equipment and rubber- tire rollers. Drilling: moderately difficult.	Infiltration: medium to rapid. Runoff: slow. Susceptibility to erosion: slight.	Permeability: medium. Water table: depth varies in outcrop area; commonly slightly above level of nearby streams. Yield to wells: reportedly as much as 45 gpm; more commonly 20 gpm. Use: reported good source locally for domestic, public supply, and stock water uses; estimated good also for industrial and cooling uses.	generally satisfactory if easily excavated material sufficient for proper burial of system; percolation generally satisfactory, locally marginal. Dump sites: poor	Good.	Good, because bed dips into nillside.	Good.	Possible source of silica sand. Reported former source of fair- quality building and grinding stone.
and siltstone ss-ms Hygiene Sandstone Member	siltstone (48 percent). Sandstone fine to very fine grained, moderately well sorted; moderately cemented at surface	Siltstone: PVC2/ rating, 0.3, noncritical; swell index, 450 psf. Bentonite: none observed. Dip of beds: 12°-20° E. in northern part of area; 85° E. to 85° W. in southern part.	Low ridge about 1 mile east of and approximately parallel to hogbacks.	In natural exposures, sandstone surface slightly case-hardened; moderately resistant to weathering; where buried by surficial deposits, surface of unit commonly altered to hard silty and clayey sand (SM, SC3/) to depth of about 2 ft below base of surficial deposit.	difficult.	Infiltration: medium to slow. Runoff: medium. Susceptibility to erosion: very slight to moderately resistant.	Permeability: low. Water table: varies greatly in depth. Yield to wells: reportedly as much as 12 gpm; more commonly 2-5 gpm. Quality: hard; iron content commonly excessive. Use: estimate fair source for domestic use; good for stock use.	Septic systems: varies, mostly unsatisfactory because easily excavated material commonly too thin for proper burial; percolation commonly satisfactory to marginal: where easily excavated material locally thick, suitability probably satisfactory. Dump sites: poor chiefly because excavation moderately difficult.	Good.	Mostly good. Poor to hazardous if bedding surfaces are undercut.	Good.	Source of olive- gray landscape rock.
and claystone ss-ms-cs Formation; Lytle Formation In the state of th	medium-grained, well sorted; composed of subrounded to rounded clear to yellowish- stained quartz; well cemented by silica and iron oxide; in upper part laminated and platy thick bedded and ripple marked; bedding moderately persistent laterally, in lower part mostly massive, cross stratified, thickness variable but	Porous, jointed parallel to bedding and fractured; major aquifer. Fractures close with depth; frequency of joints increases as bed thickness decreases. Thickest beds 6-9 ft. Claystone: PVC2/ rating, 0.8-1.5, noncritical; swell index, 800-1,300 psf. Beds of swelling bentonite very sparse. Dip of beds: generally 300-700 E., near Sunshine Gulch beds overturned to steep westward dip.	Eastern hogback and prominent ledges.	sandstone surface generally case- hardened; moderately to highly resistant to weathering; siltstone and claystone surface fractured by desiccation and release of rock pressure; moderately resistant to	generally requires blasting. Fractured and moderately to	Infiltration: medium. Runoff: medium to rapid. Susceptibility to erosion: resistant.	high near outcrops and where fractured; probably medium at depth. Water table: generally slightly above level of streams near outcrop area. Pressure gradient slopes east from outcrop area; some wells east of outcrop area flow; most have	generally unsatisfactory because easily excavated material generally too thin for proper burial of system and risk moderate of pollution passing	Excellent where hazard of rockslides on dip slope absent.	Varies. Hazardous if bedding surfaces are undercut. Loose blocks and rock debris may slide on dip slopes. Locally some danger of rockfalls along flanks of steep ridges and in cuts. Inspection for loose rock above building sites recommended.	Excellent where rock- fall and landslide hazards absent.	Source of clay for brick and tile, and of buff-colored landscape "moss" rock. Local source of fair-quality riprap.
sandstone Sundance Formation Sundance Formation Sundance Formation Sundance Formation Sundance Formation	grained, fairly well sorted, composed of subangular to rounded frosted quartz; well cemented by silica; cross-stratified, flaggy, in part ripple marked; light reddish brown. Unit includes two belts paralleling mountain front and separated by several map units each of different lithologies: eastern belt 0-20 ft thick; western belt about 250 ft.	Joints chiefly parallel to bedding; major aquifer along outcrops in mapped area. Fractures close with depth. Maximum thickness of beds: western belt 1-2 ft thick, commonly 1-3 in. thick along crossbedding; eastern belt massive. Dip of beds: 340-800 E. at outcrops.	righest ridge and prominent ledges of western hog-back; flatirons along east face of same hogback.	highly resistant to weathering; locally disintegrated chiefly by freezing and thaving of water in fractures to yield piles of fragmented rock called talus.	Excavation: difficult; requires blasting. Compaction: difficult; generally requires mixing with binder material before compacting. Hauling equipment commonly used. Drilling: very difficult.	Infiltration: medium. Runoff: medium to rapid. Susceptibility to erosion: very resistant.	Permeability: generally high near outcrops and where fractured; probably medium at depth. Water table: generally slightly above level of streams near outcrop area. Pressure gradient slopes east from outcrop area; no flowing wells reported. Yield to wells: none reported in area; probably can yield moderate quantities to wells near outcrop. Eldorado Springs reportedly flows 100 gpm. Quality: moderately hard. Use: estimated good source for domestic, public supply, stock, and certain industrial uses.	Same as for above. Dump sites: Same.	Same as for above.	Same as for above.	Same as for "Swelling claystone and siltstone (cs-ms)."	Source of good- quality building stone and riprap.
and siltstone egl-ms f s t q o c m m t t	stone (25 percent), and siltstone (10 percent): very line- to coarse-grained, poorly sorted, composed of subangular so subrounded fragments of quartzite and grainte and grains of quartz, feldspar, mica, and clay minerals (kaolinite and dixed-layer illite-	assive, jointed parallel I to bedding, irregularly fractured. Fractures close with depth. Maximum thickness of conglomerate lenses as much as 60 ft; of siltstone, as much as 15 ft. ip of beds: 42°-53° E. at outcrops.		moderately resistant to weathering; where buried by surficial deposits, uppermost zone of unit commonly leached of cement and disintegrated to silty and clayey sand and gravel (SC, GC, SM, GM3/) to depth of about 3 ft below base of surficial	Excavation: difficult; requires blasting; possibly excavated locally with heavy tractor-drawn rippers and scrapers. Compaction: difficult; generally requires crushing and mixing with binder material before compaction. Hauling equipment and steel-wheeled rollers commonly used. Drilling: difficult.	Susceptibility to erosion: resistant.	Permeability: generally low; probably medium where faulted and fractured. Water table: slightly above level of streams in fractures of rocks near outcrops. Yield to wells: commonly yields from less than 1 to 5 gpm; locally as much as 15 gpm reported. Underlying weathered and fractured zone in igneous and metamorphic rocks (chiefly gt, bg) probably can yield moderate quantities. Quality: hard; iron and manganese content high. Use: estimated generally fair to poor source for domestic use; good source for stock use.	generally unsatisfactory because easily excavated material commonly too thin for proper burial of system, and percolation commonly too slow, locally marginal; risk moderate of pollution passing through fractures into water supplies.	Excellent.	Usually good. Loose blocks and rock debris may slide on dip slope if support removed.	Excellent.	Source of pink- colored landscape "moss" rock.
(part): Fort Hays Limestone Member; Lykins Formation (part): Glennon Limestone Member be so that the second secon	inely to coarsely crystalline, lensely indurated, very hard. Is punit includes two belts paralleling mountain front and reparated by many other map units of different lithologies: reastern belt, gray limestone; reds as much as 4 ft thick, smooth, even, persistent	to bedding; possible minor aquifer. Rocks in eastern belt blocky, as much as 3 ft thick; in western belt irregularly fractured across 1/8- to 1-inthick laminae and beds. ip of beds: 25°-85° E.	hogbacks along valley formed by "Red siltstone (ms)" and about 1/2 mile east of and approximately parallel to hogbacks.	moderately resistant to mechanical weathering; generally surface roughened and pitted by solution.	requires blasting. Compaction: difficult;	Runoff: medium to rapid. Susceptibility to erosion: resistant.	Permeability: medium to high along fractures. Water table: varies widely in lateral extent. Artesian rise locally in wells. Yield to wells: probably as much as 25 gpm locally. Encrustation on well intakes may reduce	Septic systems: generally unsatisfactory because cover commonly too thin for proper burial of system, and risk high of pollution passing through fractures into water supplies. Dump sites: very poor because excavation difficult and risk high of ground-water pollution in outcrop area.	xcellent.	Generally good. Loose blocks may slide on dip slope if support removed.		Western belt reported as former local source of agricultural lime. Eastern belt source for limited quantities of raw material for cement; good-quality crushed aggregate.